July 8, 2014

Pretty Disgusting!

Remember, Marty has already made his deal with the government. He will be on the witness stand testifying against me in the event of a trial. He may have slowed down a little bit with his selling of updated software hard drives, but he definitely did not stop.





LMVIND Original Post: 2006 251 R-Class: Engine: SDS wont connec...

Tue, Jul 8, 2014 at 12:20 PM

VIN: 4JGCB65E76A006939 Model Type: 251 R-Class

Model Year: 2006

Engine Type: R350 4MATIC 251.165 272.967 Trans Type: 722.9 6 Speed Automatic Electronic

Mileage: 183103 Category: Engine

Area - DTC Codes (engine)

Malfunction - SDS wont connect to car

Condition - always

History - Just swapped out hard drive with new SDS from LMV.

I am trying to connect the SDS to this R class but it stops and says diagnostic multiplexer cannot initialize. I can connect the SDS to the ML I also have here and it connects to it just fine. I have also used a regular OBD2 scanner and it does work on the R class to read ecu faults. We just updated the software via a new hard drive from LMV and I am wondering if

this is a software setup issue before I charge the customer for diagnostics.

Thanks,





REMINDER ON POSTING ISSUES ON LMV

LMVINFO SYSTEM <contact@Imvind.com>

Tue, Jul 8, 2014 at 2:30 PM

A message from Administration

HELLO GROUP UNDER NO CIRCUMSTANCES YOU ARE TO POST ANY OF THE FOLLOWING ON THE LMV POSTING PAGE:

REQUEST FOR ANY CODING OR PROGRAMING

PERSONAL PHONE REQUEST TO SPEAK TO ME DIRECTLY

ANY SOFTWARE, HARDWARE OR SDS RELATED ISSUES THAT IS NOT RELATED TO A COMPUTER OR CONTROLLER ON A VEHICLE

USING THE POSTING PAGES TO COMMUNICATE WITH SOMEONE DIRECTLY

I WILL SUSPEND THE ACCOUNT IF THESE RULES ARE NOT FOLLOWED

THANK YOU

MARTY, LMV TECH SUPPORT TEAM

FROM ADMINISTRATION AT LMV INFO SYSTEM

Email us at Contact@Imvind.com

Rainer

From:

Sent:

Tuesday, October 23, 2018 12:00 PM

To:

rainer@brinsonco.com

Subject:

FW: LMVIND Update Post: 2007 209 CLK: Engine: -...

Reply To Member: Larry Flowers

VIN: WDBTJ56H87F209321

Model Type: 209 CLK Model Year: 2007

Engine Type: 272 6-cyl V-6

Trans Type: 722.6 - Automatic Electronic 5-Speed

Mileage: 108570 Area - Mechanical

History - None

Update
ok sent to have the timing and shaft replaced.
Original

had check engine light on. scan and see has 1200,1208,(p0016,p0017) for constant adjustment of inlet camshaft right bank, clear and comes right back. I think this need to have camshaft timing check for being out of time first am correct. keeps setting fault sitting in the shop without driving...

also, Marty, have my new hard drive install ready for to log on..

LMV Sponsoring Gold Member Larry Flowers Flowers Automotive Specialists,Inc. lwflowers1@juno.com

10/23/2018 - 9:29:35 AM

Confidentiality Notice: This e-mail message is for the sole use of the intended recipient(s) and contains confidential and privileged information, specifically the sender's email address. The use of this information is restricted to the terms described in LMV's Acceptable Use Policy. Any unauthorized review, use, disclosure, distribution or copyright infringement is prohibited.